



# Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

January 6, 1958

BULLETIN NO. 159

TO: All Distributing Office Service Personnel

SUBJECT: Burning of Segments on F-5515 Switch Circuit Assembly

In order to eliminate arcing between the credit switch segments of the credit unit commutator plate and the wiper blades when the credit unit is set up to operate on five-cent play, the following procedure is recommended:

Connect the large (center) "ten-cent" credit switch segment to the "fifteen-cent or more" segment (large outside segment). This connection may be conveniently made by placing a jumper between terminals 8 and 9 of the ten-prong Jones plug.

This remedy may be used only when no extended play selections are being offered at a premium price.

The arcing does not occur when price combinations are used which do not involve "five-cent" play.

APPLICATIONS ENGINEERING

/hr