



Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

September 23, 1955

BULLETIN NO. 114

TO: All Distributing Office Service Personnel

SUBJECT: Light Diffuser

The white plastic, light diffuser material, which is stored behind the record rack and installed after unpacking, may have a tendency to curl due to temperature changes. It may be necessary to either lay it on a flat surface over night or install it between the support rails in the phonograph and temporarily tape the ends to the rails.

If the material is too short, because of its being rolled for shipment, it may be lengthened by stretching. If it is too long, simply cut off the excess at one of the folds with a pair of ordinary household scissors.

APPLICATIONS ENGINEERING