



Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

April 10, 1956

BULLETIN NO. 118

TO: All Distributors

SUBJECT: Credit Unit Reset Magnets

The reset magnet in the R-299 Credit Unit of all "G-80" and "G-120" Phonographs has been changed. The reset magnet now being used bears the part number F-3234 and replaces the F-650 Reset Magnet formerly used. The change is effective approximately with the following serial numbers: "G-80" - 310897, "G-120" - 322642.

The F-3234 is the same reset magnet which, under part number F-1939, was recommended as a replacement for the F-650 Reset Magnet in cases where machines were being cheated by light tapping on the selector pushbuttons.

In field cases, where the F-1939 is required to replace an F-650, it may now be ordered from the factory under its new part number, F-3234.

APPLICATIONS ENGINEERING

/hc