

AMI

Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

October 23, 1958

BULLETIN NO. 169

SUBJECT: PF-58 Replacement Inner Shoes for Model 700 & 800 Mechanisms

This is to call your attention to the fact that replacement inner shoes for Model 700 and 800 Mechanisms now have grippers made of nylon instead of cast metal.

These new inner shoes are Part Number PF-58.

APPLICATIONS ENGINEERING

CLB/hr