



Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

April 15, 1959

BULLETIN NO. 175

SUBJECT: Replacement Turntable Motors

Turntable motors used on machines prior to the late Model "I's" have been discontinued by our suppliers. Exact replacement motors and parts are no longer available for some models.

The H-1836 Motor used on late Model "I's" and on the Model "J" is mounted onto the turntable bearing plate with snap rings instead of screws. These motors will not fit the standard bearing plates on earlier models.

Special bearing plates have been made to adapt the H-1836 Motor to earlier machines. These will be supplied at no extra cost when motors are ordered for the early models.

Since there are slight differences from model to model, one adaptor plate cannot accommodate all. Therefore it is very important to specify the model of the machine the turntable motor is to be used on when replacements are ordered.

APPLICATIONS ENGINEERING

CLE/mal