

SERVICE BULLETIN

AUTOMATIC MUSIC, INC.

1500 UNION AVENUE. S. E., GRAND RAPIDS 2, MICHIGAN • TELEPHONE CHERRY 3-3633

AFFILIATE OF **AUTOMATIC CANTEN COMPANY** of AMERICA

AMI

October 9, 1961

SERVICE BULLETIN #193

Subject: PF-189 Turntable Idler and Link Assembly.
Replacement for F-898 Idler pulley.

The F-898 turntable idler pulley used on Models F through CONTINENTAL 1 is no longer available. In its place we will furnish a PF-189 turntable idler and link assembly.

This assembly consists of an F-8006A idler - as used on the CONTINENTAL 2 - and a link which will adapt it for mounting on the earlier turntables.

Cliff L. Bitting
FIELD SERVICE ENGINEERING

CLB:emc