

# SERVICE BULLETIN

AUTOMATIC MUSIC, INC.

1500 UNION AVENUE. S. E., GRAND RAPIDS 2, MICHIGAN • TELEPHONE CHERRY 3-3633



July 6, 1960

BULLETIN NO. 185  
Model "K"

SUBJECT: Mounting of CCA, CCB, CCC, & CCD Steppers

When any of subject steppers are mounted in the phonograph, they must be allowed to "float" on the rubber grommets in their mounting brackets.

If the thumbscrews which hold down the front brackets are tightened too much, the frame of the unit will be warped and cause the number stepper to fail.

Make sure these screws are not tightened enough to compress the rubber grommets in the front mounting brackets.

APPLICATIONS ENGINEERING

CLB/hr