



Service Bulletin

AMI INCORPORATED • 1500 UNION AVENUE, S. E. • GRAND RAPIDS 2, MICHIGAN

April 10, 1957

BULLETIN NO. 138

TO: All Distributing Office Service Personnel

SUBJECT: Pin Pusher Assembly on JCH-100 Phonographs

This bulletin is to call your attention to the fact that the even pin pusher, on the JCH-100 only, is offset to provide registration with the selector pins.

Do not straighten this pin pusher.

On the JAH-200 and JBH-120, both pin pushers are straight.

APPLICATIONS ENGINEERING

CLB/hc