

# SERVICE BULLETIN

## AUTOMATIC MUSIC, INC.

1500 UNION AVENUE, S. E., GRAND RAPIDS 2, MICHIGAN • TELEPHONE CHERRY 3-3633



AFFILIATE OF AUTOMATIC CANTEEN COMPANY of AMERICA

May 15, 1961

### BULLETIN # 190

#### PF-187 REPLACEMENT PARTS GROUP FOR THE AUTO MIX

We can no longer supply the F-10379 sensing switch nor the F-10378A switch lever used on the first production run of Auto Mixes.

A group of parts consisting of a new switch, switch lever, mounting bracket, hardware, and instructions has been prepared for use when it is necessary to replace either of the above mentioned original parts. This parts group should be ordered under the number PF-187.

FIELD SERVICE ENGINEERING